W	⁷ ork	Or	der	ID	55879
---	------------------	----	-----	----	-------



Page 1

February 3, 2010 1:48:49 PM

Item ID:

D4027-5

Accept

Setup Start

Revision ID:

Item Name:

Rubber Cushion

Start Date: 2/03/10 Required Date: 2/10/10 Start Qty: 2.00

Req'd Qty: 2.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:10-2-03

Date:

Tooling: SPC (Y/N): Date:

Date:

Run Start

Stop

Stop

Sequence ID/ Work Center ID Operation Description Set Up/ **Run Hours** Draw Number

Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Insp. Number Stamp

Draw Nbr

Revision Nbr

QC:

D4027

A-PRELIM

0.00

100

Waterjet

Memo

0.00

FLOW CNC Waterjet

1-Cut as per Dwg Dwg Rev: DR Prog Rev:

2-Deburr if necessary

110

QC2- Inspect parts off machine FAI/FAIB

0.00

Quality Control

Memo

0.00

B 10-2-11

B 10-2-11



Dart Aerospace Ltd W/O: **WORK ORDER CHANGES** Approval Chief Eng / Prod Mgr Approval DATE STEP **PROCEDURE CHANGE** Bv Date **D**tv QC Inspector Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: _____ Resolution: _____ QA: N/C Closed: ____ Date: _____ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval STEP Approval** DATE **Action Description** Sign & Initial Section A QC Inspector Section C Chief Eng Chief Eng Date Chief Eng

Work Order ID 55879

February 3, 2010 1:48:49 PM



Page 2

Item ID:

D4027-5

Accept

Setup Start

Stop

Revision ID: Item Name:

Rubber Cushion

Start Date:

2/03/10

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



Required Date: 2/10/10

QC:

Date:_____

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Qty

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Memo

Memo

0.00

Eroloshia

Draw

Number

Draw Plan Rev. Code Accept **Qty**

Reject Reject Number

Insp. Stamp

0.00

170

Packaging

Packaging

Identify as per dwg & Stock Location: 117

0.00

0.00

10.6.25

180

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

POSITIVE RECALL

EFFECTIVE 602 CO AUTH _

RELEASED /

10/06/28 A) W10-2-19

Duit Aciosbuce Eta	Dart	Aeros	space	Ltd
--------------------	------	--------------	-------	-----

W/O:		***	WC	ORK ORDER CHANG	FS					,
DATE	STEP	PRO	OCEDURE CHA			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										!
,										
Part No	: <u> </u>	PAR #:	Fault Cate	gory:	_ NCR	: Yes	No DQA :		Date:	
	R	esolution:	Dispositio	n:	_ QA:	N/C Cld	sed:	.	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE	(NCR)			-
DATE	CTED	Description of NC		Corrective Action Section B			Verifica		Approval	Approval
DATE	STEP Description of NC Section A		Initial Action Descrip Chief Eng Chief Eng		on Sign & Section Sect					QC Inspector
									;	
		- *								

Picklist Print

February 3, 2010 1:48:52 PM

Work Order ID: 55879

D4027-5 Parent Item:

Parent Item Name: Rubber Cushion

IPP rev A 10.02.01 new issue Prelim EC verified by:JLM

Comments:



Start Date: 2/03/10

Required Date: 2/10/10

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
MNEO60S.063		Purchased	No		,	100	sf	715.1060		.12_		· · · · · · · · · · · · · · · · · · ·
										Æ	310-2-11	

NEOPRENE SHEET 0.063

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			Ĺ.
MAT	715.106		
112508	61.6034		
112662	290.2821		
112866	154.11		
113058	209.1105		113028

Page 1

Dart Aerospace L	.td
------------------	-----

W/O:			M	VORK ORDER CHANG	ES					1
DATE	STEP	PROC	CEDURE CH	IANGE	ı	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCR:	Yes N	o DQA:		Date:	
	R	esolution:	_ Disposit	ion:	_ QA: N	I/C Clo	sed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE (NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sect Action Description Chief Eng	tion B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
						····			- Property and the second	
!										

DART AEROSPACE LTD	Work Order:	55879
Description: Rubber Custion	Part Number:	D4077-5
Inspection Dwg:D4007-4 Rev: DBK Xim Pin2		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	Pr	ototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
.75	1/020	.764	7	ļ		
5,30	4 ,020	5,323	7			
. ,06	-010	,062	6	ļ		
				-		
				 		
			·	-		
				 		
			1	-		
			-	1		
		ļ	-	 		
				ļ		
			 -	-		
			<u> </u>			
			 			
		<u> </u>	 	 		
		-	-	+	 	
			-	+		94
			-			
		+	 	-		
		+		-	<u> </u>	1
		1			1	/10:06:2

			7 Factor Americal	N/A
Measured by:	1B	Audited by:	Prototype Approval:	,
Date:	10-5-11	Date: 10/02/16	Date:	IN/A

			Revised by	Approved
Rev	Date	Change	KJ/JLM	
Α		New Issue	TOPPIN	



Dart Aerospace Ltd W/O: **WORK ORDER CHANGES** Approval Approval DATE STEP PROCEDURE CHANGE Bv **d**tv Date Chief Eng / QC Inspector Prod Mar Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: Date: _____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: _____ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** DATE **Approval** STEP Initial **Action Description** Sian & Section A Section (Chief Eng QC Inspector Chief Eng Chief Eng Date

